





CHANNEL STABILITY:

-  Stable
-  Unstable
-  Highly Unstable



1 0 1 2
MILES

EXHIBIT 6
CHANNEL STABILITY

RIO GRANDE HEADWATERS RESTORATION PROJECT
 San Luis Valley Water Conservancy District
 Colorado Water Conservation Board

MONTGOMERY WATSON
 Lidstone & Associates, Inc.
 SLV GIS/GPS Authority Board

Agro Engineering, Inc.
SWCA, Inc.
 Davis Engineering

CONEJOS COUNTY